

**Land Assemblage Redevelopment Authority RFP**  
**Attachment L**  
**Lot Inspections**

<b>Area</b>	<b>HCAD</b>	<b>COH Tract #:</b>	<b>Survey Date:</b>
Third Ward	0521900000001	2564	May 18, 2006

<b>Address No.</b>	<b>Prefix</b>	<b>Street Name</b>	<b>St. Type</b>	<b>Suffix</b>
2800		DENNIS		

<b>Curb Cut</b> <b>Lot A (left)</b> <input type="checkbox"/> <i>Existing Curb Cut</i> <input checked="" type="checkbox"/> <i>No existing curb cut</i> <b>Lot B (If applicable-right)</b> <input type="checkbox"/> <i>Existing curb cut</i> <input type="checkbox"/> <i>No existing curb cut</i> <input type="checkbox"/> <i>Parcel is only one lot</i> <b>Lot C (If applicable-furthest right)</b> <input type="checkbox"/> <i>Existing curb cut</i> <input type="checkbox"/> <i>No existing curb cut</i> <input type="checkbox"/> <i>Parcel is only one lot</i>				
<b>Street Edge (Prevailing on Street)</b> <input type="checkbox"/> <i>Sidewalks</i> <input type="checkbox"/> <i>Ditch and Culverts</i>				
<b>Trees Located in Right-of-Way</b> <input type="checkbox"/> <i>No trees observed in ROW</i> <input type="checkbox"/> <i>Less than 3 trees</i> <input checked="" type="checkbox"/> <i>Greater than 3 trees</i>				
<b>Trees (&gt;8" Caliper located on Site)</b> <input type="checkbox"/> <i>No trees</i> <input type="checkbox"/> <i>Less than 3 trees</i> <input type="checkbox"/> <i>Greater than 3 trees</i>				
<b>Existing Slab or Paving Removal</b> <input type="checkbox"/> <i>Existing slab/pavement &lt;10'-0" x 10'-0"</i> <input checked="" type="checkbox"/> <i>Existing slab/pavement &gt;10'-0" x 10'-0"</i> <input type="checkbox"/> <i>Existing pier and beam</i>				
<b>Existing Building Removal</b> <input type="checkbox"/> <i>Existing structure &lt;10'-0" x 10'-0"</i> <input type="checkbox"/> <i>Existing structure &gt;10'-0" x 10'-0"</i> <input type="checkbox"/> <i>Existing pier and beam</i>				
<b>Septic Tanks</b> <input type="checkbox"/> <i>Septic tanks visually identified</i> <input checked="" type="checkbox"/> <i>No visual evidence of septic tank</i>				
<b>Wells</b> <input type="checkbox"/> <i>Well visually identified</i> <input checked="" type="checkbox"/> <i>No visual evidence of well</i>				
<b>Vegetation, Trash or Debris Removal</b> <input type="checkbox"/> <i>Planting and debris &lt;10 cubic yards</i> <input checked="" type="checkbox"/> <i>Planting and debris &gt; 10 cubic yards</i>				
<b>Existing Fences on Site</b> <input type="checkbox"/> <i>Chain Link Fence</i> <input type="checkbox"/> <i>Wood Fence</i> <input type="checkbox"/> <i>Wrought Iron/Metal Fence</i>				
<b>Power Poles - Front of Lot/Back of Lot</b> <input checked="" type="checkbox"/> <i>Power pole located at front of lot</i> <input type="checkbox"/> <i>Power pole located in ROW at back of lot</i> <input type="checkbox"/> <i>No power pole visible on lot</i>				
<b>Drainage</b> <input type="checkbox"/> <i>Lot visibly slopes from back to front</i> <input type="checkbox"/> <i>Lot visibly slopes from front to back</i> <input checked="" type="checkbox"/> <i>Can't tell/Unable to visually determine slope</i>				

**Land Assemblage Redevelopment Authority RFP**  
**Attachment L**  
**Lot Inspections**

<b>Area</b>	<b>HCAD</b>	<b>COH Tract #:</b>	<b>Survey Date:</b>
Third Ward	0372550000005	2568	May 18, 2006

<b>Address No.</b>	<b>Prefix</b>	<b>Street Name</b>	<b>St. Type</b>	<b>Suffix</b>
3328		DENNIS		

<b>Curb Cut</b> <b>Lot A (left)</b> <input checked="" type="checkbox"/> <i>Existing Curb Cut</i> <input type="checkbox"/> <i>No existing curb cut</i> <b>Lot B (If applicable-right)</b> <input type="checkbox"/> <i>Existing curb cut</i> <input type="checkbox"/> <i>No existing curb cut</i> <input type="checkbox"/> <i>Parcel is only one lot</i> <b>Lot C (If applicable-furthest right)</b> <input type="checkbox"/> <i>Existing curb cut</i> <input type="checkbox"/> <i>No existing curb cut</i> <input type="checkbox"/> <i>Parcel is only one lot</i>	
<b>Street Edge (Prevailing on Street)</b> <input checked="" type="checkbox"/> <i>Sidewalks</i> <input type="checkbox"/> <i>Ditch and Culverts</i>	
<b>Trees Located in Right-of-Way</b> <input type="checkbox"/> <i>No trees observed in ROW</i> <input type="checkbox"/> <i>Less than 3 trees</i> <input type="checkbox"/> <i>Greater than 3 trees</i>	
<b>Trees (&gt;8" Caliper located on Site)</b> <input type="checkbox"/> <i>No trees</i> <input type="checkbox"/> <i>Less than 3 trees</i> <input checked="" type="checkbox"/> <i>Greater than 3 trees</i>	
<b>Existing Slab or Paving Removal</b> <input type="checkbox"/> <i>Existing slab/pavement &lt;10'-0" x 10'-0"</i> <input type="checkbox"/> <i>Existing slab/pavement &gt;10'-0" x 10'-0"</i> <input type="checkbox"/> <i>Existing pier and beam</i>	
<b>Existing Building Removal</b> <input type="checkbox"/> <i>Existing structure &lt;10'-0" x 10'-0"</i> <input type="checkbox"/> <i>Existing structure &gt;10'-0" x 10'-0"</i> <input type="checkbox"/> <i>Existing pier and beam</i>	
<b>Septic Tanks</b> <input type="checkbox"/> <i>Septic tanks visually identified</i> <input checked="" type="checkbox"/> <i>No visual evidence of septic tank</i>	
<b>Wells</b> <input type="checkbox"/> <i>Well visually identified</i> <input checked="" type="checkbox"/> <i>No visual evidence of well</i>	
<b>Vegetation, Trash or Debris Removal</b> <input type="checkbox"/> <i>Planting and debris &lt;10 cubic yards</i> <input type="checkbox"/> <i>Planting and debris &gt; 10 cubic yards</i>	
<b>Existing Fences on Site</b> <input type="checkbox"/> <i>Chain Link Fence</i> <input type="checkbox"/> <i>Wood Fence</i> <input type="checkbox"/> <i>Wrought Iron/Metal Fence</i>	
<b>Power Poles - Front of Lot/Back of Lot</b> <input checked="" type="checkbox"/> <i>Power pole located at front of lot</i> <input type="checkbox"/> <i>Power pole located in ROW at back of lot</i> <input type="checkbox"/> <i>No power pole visible on lot</i>	
<b>Drainage</b> <input type="checkbox"/> <i>Lot visibly slopes from back to front</i> <input type="checkbox"/> <i>Lot visibly slopes from front to back</i> <input checked="" type="checkbox"/> <i>Can't tell/Unable to visually determine slope</i>	

**Land Assemblage Redevelopment Authority RFP**  
**Attachment L**  
**Lot Inspections**

<b>Area</b>	<b>HCAD</b>	<b>COH Tract #:</b>	<b>Survey Date:</b>
Third Ward	0190520010010	5515	May 18, 2006

<b>Address No.</b>	<b>Prefix</b>	<b>Street Name</b>	<b>St. Type</b>	<b>Suffix</b>
2613		DOWLING	ST	

<b>Curb Cut</b> <b>Lot A (left)</b> <input checked="" type="checkbox"/> <i>Existing Curb Cut</i> <input type="checkbox"/> <i>No existing curb cut</i> <b>Lot B (If applicable-right)</b> <input type="checkbox"/> <i>Existing curb cut</i> <input type="checkbox"/> <i>No existing curb cut</i> <input type="checkbox"/> <i>Parcel is only one lot</i> <b>Lot C (If applicable-furthest right)</b> <input type="checkbox"/> <i>Existing curb cut</i> <input type="checkbox"/> <i>No existing curb cut</i> <input type="checkbox"/> <i>Parcel is only one lot</i>	
<b>Street Edge (Prevailing on Street)</b> <input checked="" type="checkbox"/> <i>Sidewalks</i> <input type="checkbox"/> <i>Ditch and Culverts</i>	
<b>Trees Located in Right-of-Way</b> <input type="checkbox"/> <i>No trees observed in ROW</i> <input type="checkbox"/> <i>Less than 3 trees</i> <input type="checkbox"/> <i>Greater than 3 trees</i>	
<b>Trees (&gt;8" Caliper located on Site)</b> <input checked="" type="checkbox"/> <i>No trees</i> <input type="checkbox"/> <i>Less than 3 trees</i> <input type="checkbox"/> <i>Greater than 3 trees</i>	
<b>Existing Slab or Paving Removal</b> <input type="checkbox"/> <i>Existing slab/pavement &lt;10'-0" x 10'-0"</i> <input type="checkbox"/> <i>Existing slab/pavement &gt;10'-0" x 10'-0"</i> <input type="checkbox"/> <i>Existing pier and beam</i>	
<b>Existing Building Removal</b> <input type="checkbox"/> <i>Existing structure &lt;10'-0" x 10'-0"</i> <input type="checkbox"/> <i>Existing structure &gt;10'-0" x 10'-0"</i> <input type="checkbox"/> <i>Existing pier and beam</i>	
<b>Septic Tanks</b> <input type="checkbox"/> <i>Septic tanks visually identified</i> <input checked="" type="checkbox"/> <i>No visual evidence of septic tank</i>	
<b>Wells</b> <input type="checkbox"/> <i>Well visually identified</i> <input checked="" type="checkbox"/> <i>No visual evidence of well</i>	
<b>Vegetation, Trash or Debris Removal</b> <input type="checkbox"/> <i>Planting and debris &lt;10 cubic yards</i> <input type="checkbox"/> <i>Planting and debris &gt; 10 cubic yards</i>	
<b>Existing Fences on Site</b> <input type="checkbox"/> <i>Chain Link Fence</i> <input type="checkbox"/> <i>Wood Fence</i> <input type="checkbox"/> <i>Wrought Iron/Metal Fence</i>	
<b>Power Poles - Front of Lot/Back of Lot</b> <input checked="" type="checkbox"/> <i>Power pole located at front of lot</i> <input type="checkbox"/> <i>Power pole located in ROW at back of lot</i> <input type="checkbox"/> <i>No power pole visible on lot</i>	
<b>Drainage</b> <input type="checkbox"/> <i>Lot visibly slopes from back to front</i> <input type="checkbox"/> <i>Lot visibly slopes from front to back</i> <input checked="" type="checkbox"/> <i>Can't tell/Unable to visually determine slope</i>	

**Land Assemblage Redevelopment Authority RFP**  
**Attachment L**  
**Lot Inspections**

<b>Area</b>	<b>HCAD</b>	<b>COH Tract #:</b>	<b>Survey Date:</b>
Third Ward	0101640000005	2657	May 18, 2006

<b>Address No.</b>	<b>Prefix</b>	<b>Street Name</b>	<b>St. Type</b>	<b>Suffix</b>
0		HADLEY		

<b>Curb Cut</b> <b>Lot A (left)</b> <input checked="" type="checkbox"/> <i>Existing Curb Cut</i> <input type="checkbox"/> <i>No existing curb cut</i> <b>Lot B (If applicable-right)</b> <input type="checkbox"/> <i>Existing curb cut</i> <input type="checkbox"/> <i>No existing curb cut</i> <input type="checkbox"/> <i>Parcel is only one lot</i> <b>Lot C (If applicable-furthest right)</b> <input type="checkbox"/> <i>Existing curb cut</i> <input type="checkbox"/> <i>No existing curb cut</i> <input type="checkbox"/> <i>Parcel is only one lot</i>	
<b>Street Edge (Prevailing on Street)</b> <input type="checkbox"/> <i>Sidewalks</i> <input type="checkbox"/> <i>Ditch and Culverts</i>	
<b>Trees Located in Right-of-Way</b> <input type="checkbox"/> <i>No trees observed in ROW</i> <input type="checkbox"/> <i>Less than 3 trees</i> <input type="checkbox"/> <i>Greater than 3 trees</i>	
<b>Trees (&gt;8" Caliper located on Site)</b> <input type="checkbox"/> <i>No trees</i> <input type="checkbox"/> <i>Less than 3 trees</i> <input checked="" type="checkbox"/> <i>Greater than 3 trees</i>	
<b>Existing Slab or Paving Removal</b> <input type="checkbox"/> <i>Existing slab/pavement &lt;10'-0" x 10'-0"</i> <input type="checkbox"/> <i>Existing slab/pavement &gt;10'-0" x 10'-0"</i> <input type="checkbox"/> <i>Existing pier and beam</i>	
<b>Existing Building Removal</b> <input type="checkbox"/> <i>Existing structure &lt;10'-0" x 10'-0"</i> <input type="checkbox"/> <i>Existing structure &gt;10'-0" x 10'-0"</i> <input type="checkbox"/> <i>Existing pier and beam</i>	
<b>Septic Tanks</b> <input type="checkbox"/> <i>Septic tanks visually identified</i> <input checked="" type="checkbox"/> <i>No visual evidence of septic tank</i>	
<b>Wells</b> <input type="checkbox"/> <i>Well visually identified</i> <input checked="" type="checkbox"/> <i>No visual evidence of well</i>	
<b>Vegetation, Trash or Debris Removal</b> <input type="checkbox"/> <i>Planting and debris &lt;10 cubic yards</i> <input type="checkbox"/> <i>Planting and debris &gt; 10 cubic yards</i>	
<b>Existing Fences on Site</b> <input checked="" type="checkbox"/> <i>Chain Link Fence</i> <input type="checkbox"/> <i>Wood Fence</i> <input type="checkbox"/> <i>Wrought Iron/Metal Fence</i>	
<b>Power Poles - Front of Lot/Back of Lot</b> <input type="checkbox"/> <i>Power pole located at front of lot</i> <input type="checkbox"/> <i>Power pole located in ROW at back of lot</i> <input checked="" type="checkbox"/> <i>No power pole visible on lot</i>	
<b>Drainage</b> <input type="checkbox"/> <i>Lot visibly slopes from back to front</i> <input type="checkbox"/> <i>Lot visibly slopes from front to back</i> <input checked="" type="checkbox"/> <i>Can't tell/Unable to visually determine slope</i>	

**Land Assemblage Redevelopment Authority RFP**  
**Attachment L**  
**Lot Inspections**

<b>Area</b>	<b>HCAD</b>	<b>COH Tract #:</b>	<b>Survey Date:</b>
Third Ward	0372200000004	2592	May 18, 2006

<b>Address No.</b>	<b>Prefix</b>	<b>Street Name</b>	<b>St. Type</b>	<b>Suffix</b>
3124		MC ILHENNY		

<b>Curb Cut</b> <b>Lot A (left)</b> <input type="checkbox"/> <i>Existing Curb Cut</i> <input checked="" type="checkbox"/> <i>No existing curb cut</i> <b>Lot B (If applicable-right)</b> <input type="checkbox"/> <i>Existing curb cut</i> <input type="checkbox"/> <i>No existing curb cut</i> <input type="checkbox"/> <i>Parcel is only one lot</i> <b>Lot C (If applicable-furthest right)</b> <input type="checkbox"/> <i>Existing curb cut</i> <input type="checkbox"/> <i>No existing curb cut</i> <input type="checkbox"/> <i>Parcel is only one lot</i>	
<b>Street Edge (Prevailing on Street)</b> <input checked="" type="checkbox"/> <i>Sidewalks</i> <input type="checkbox"/> <i>Ditch and Culverts</i>	
<b>Trees Located in Right-of-Way</b> <input type="checkbox"/> <i>No trees observed in ROW</i> <input type="checkbox"/> <i>Less than 3 trees</i> <input type="checkbox"/> <i>Greater than 3 trees</i>	
<b>Trees (&gt;8" Caliper located on Site)</b> <input type="checkbox"/> <i>No trees</i> <input checked="" type="checkbox"/> <i>Less than 3 trees</i> <input type="checkbox"/> <i>Greater than 3 trees</i>	
<b>Existing Slab or Paving Removal</b> <input type="checkbox"/> <i>Existing slab/pavement &lt;10'-0" x 10'-0"</i> <input type="checkbox"/> <i>Existing slab/pavement &gt;10'-0" x 10'-0"</i> <input type="checkbox"/> <i>Existing pier and beam</i>	
<b>Existing Building Removal</b> <input type="checkbox"/> <i>Existing structure &lt;10'-0" x 10'-0"</i> <input type="checkbox"/> <i>Existing structure &gt;10'-0" x 10'-0"</i> <input type="checkbox"/> <i>Existing pier and beam</i>	
<b>Septic Tanks</b> <input type="checkbox"/> <i>Septic tanks visually identified</i> <input type="checkbox"/> <i>No visual evidence of septic tank</i>	
<b>Wells</b> <input type="checkbox"/> <i>Well visually identified</i> <input type="checkbox"/> <i>No visual evidence of well</i>	
<b>Vegetation, Trash or Debris Removal</b> <input type="checkbox"/> <i>Planting and debris &lt;10 cubic yards</i> <input type="checkbox"/> <i>Planting and debris &gt; 10 cubic yards</i>	
<b>Existing Fences on Site</b> <input checked="" type="checkbox"/> <i>Chain Link Fence</i> <input type="checkbox"/> <i>Wood Fence</i> <input type="checkbox"/> <i>Wrought Iron/Metal Fence</i>	
<b>Power Poles - Front of Lot/Back of Lot</b> <input checked="" type="checkbox"/> <i>Power pole located at front of lot</i> <input type="checkbox"/> <i>Power pole located in ROW at back of lot</i> <input type="checkbox"/> <i>No power pole visible on lot</i>	
<b>Drainage</b> <input type="checkbox"/> <i>Lot visibly slopes from back to front</i> <input type="checkbox"/> <i>Lot visibly slopes from front to back</i> <input checked="" type="checkbox"/> <i>Can't tell/Unable to visually determine slope</i>	

**Land Assemblage Redevelopment Authority RFP**  
**Attachment L**  
**Lot Inspections**

<b>Area</b>	<b>HCAD</b>	<b>COH Tract #:</b>	<b>Survey Date:</b>
Third Ward	0510290000019	2566	May 18, 2006

<b>Address No.</b>	<b>Prefix</b>	<b>Street Name</b>	<b>St. Type</b>	<b>Suffix</b>
0		ROSALIE		

<b>Curb Cut</b> <b>Lot A (left)</b> <input type="checkbox"/> <i>Existing Curb Cut</i> <input checked="" type="checkbox"/> <i>No existing curb cut</i> <b>Lot B (If applicable-right)</b> <input type="checkbox"/> <i>Existing curb cut</i> <input type="checkbox"/> <i>No existing curb cut</i> <input type="checkbox"/> <i>Parcel is only one lot</i> <b>Lot C (If applicable-furthest right)</b> <input type="checkbox"/> <i>Existing curb cut</i> <input type="checkbox"/> <i>No existing curb cut</i> <input type="checkbox"/> <i>Parcel is only one lot</i>	
<b>Street Edge (Prevailing on Street)</b> <input type="checkbox"/> <i>Sidewalks</i> <input type="checkbox"/> <i>Ditch and Culverts</i>	
<b>Trees Located in Right-of-Way</b> <input type="checkbox"/> <i>No trees observed in ROW</i> <input type="checkbox"/> <i>Less than 3 trees</i> <input type="checkbox"/> <i>Greater than 3 trees</i>	
<b>Trees (&gt;8" Caliper located on Site)</b> <input type="checkbox"/> <i>No trees</i> <input type="checkbox"/> <i>Less than 3 trees</i> <input type="checkbox"/> <i>Greater than 3 trees</i>	
<b>Existing Slab or Paving Removal</b> <input checked="" type="checkbox"/> <i>Existing slab/pavement &lt;10'-0" x 10'-0"</i> <input type="checkbox"/> <i>Existing slab/pavement &gt;10'-0" x 10'-0"</i> <input type="checkbox"/> <i>Existing pier and beam</i>	
<b>Existing Building Removal</b> <input type="checkbox"/> <i>Existing structure &lt;10'-0" x 10'-0"</i> <input type="checkbox"/> <i>Existing structure &gt;10'-0" x 10'-0"</i> <input type="checkbox"/> <i>Existing pier and beam</i>	
<b>Septic Tanks</b> <input checked="" type="checkbox"/> <i>Septic tanks visually identified</i> <input type="checkbox"/> <i>No visual evidence of septic tank</i>	
<b>Wells</b> <input type="checkbox"/> <i>Well visually identified</i> <input checked="" type="checkbox"/> <i>No visual evidence of well</i>	
<b>Vegetation, Trash or Debris Removal</b> <input type="checkbox"/> <i>Planting and debris &lt;10 cubic yards</i> <input checked="" type="checkbox"/> <i>Planting and debris &gt; 10 cubic yards</i>	
<b>Existing Fences on Site</b> <input type="checkbox"/> <i>Chain Link Fence</i> <input type="checkbox"/> <i>Wood Fence</i> <input type="checkbox"/> <i>Wrought Iron/Metal Fence</i>	
<b>Power Poles - Front of Lot/Back of Lot</b> <input type="checkbox"/> <i>Power pole located at front of lot</i> <input type="checkbox"/> <i>Power pole located in ROW at back of lot</i> <input checked="" type="checkbox"/> <i>No power pole visible on lot</i>	
<b>Drainage</b> <input checked="" type="checkbox"/> <i>Lot visibly slopes from back to front</i> <input type="checkbox"/> <i>Lot visibly slopes from front to back</i> <input type="checkbox"/> <i>Can't tell/Unable to visually determine slope</i>	

**Land Assemblage Redevelopment Authority RFP**  
**Attachment L**  
**Lot Inspections**

<b>Area</b>	<b>HCAD</b>	<b>COH Tract #:</b>	<b>Survey Date:</b>
Third Ward	0510290000012	2565	May 18, 2006

<b>Address No.</b>	<b>Prefix</b>	<b>Street Name</b>	<b>St. Type</b>	<b>Suffix</b>
3209		ROSALIE		

<b>Curb Cut</b> <b>Lot A (left)</b> <input type="checkbox"/> <i>Existing Curb Cut</i> <input checked="" type="checkbox"/> <i>No existing curb cut</i> <b>Lot B (If applicable-right)</b> <input type="checkbox"/> <i>Existing curb cut</i> <input type="checkbox"/> <i>No existing curb cut</i> <input type="checkbox"/> <i>Parcel is only one lot</i> <b>Lot C (If applicable-furthest right)</b> <input type="checkbox"/> <i>Existing curb cut</i> <input type="checkbox"/> <i>No existing curb cut</i> <input type="checkbox"/> <i>Parcel is only one lot</i>				
<b>Street Edge (Prevailing on Street)</b> <input type="checkbox"/> <i>Sidewalks</i> <input type="checkbox"/> <i>Ditch and Culverts</i>				
<b>Trees Located in Right-of-Way</b> <input type="checkbox"/> <i>No trees observed in ROW</i> <input type="checkbox"/> <i>Less than 3 trees</i> <input type="checkbox"/> <i>Greater than 3 trees</i>				
<b>Trees (&gt;8" Caliper located on Site)</b> <input type="checkbox"/> <i>No trees</i> <input checked="" type="checkbox"/> <i>Less than 3 trees</i> <input type="checkbox"/> <i>Greater than 3 trees</i>				
<b>Existing Slab or Paving Removal</b> <input type="checkbox"/> <i>Existing slab/pavement &lt;10'-0" x 10'-0"</i> <input type="checkbox"/> <i>Existing slab/pavement &gt;10'-0" x 10'-0"</i> <input type="checkbox"/> <i>Existing pier and beam</i>				
<b>Existing Building Removal</b> <input type="checkbox"/> <i>Existing structure &lt;10'-0" x 10'-0"</i> <input type="checkbox"/> <i>Existing structure &gt;10'-0" x 10'-0"</i> <input type="checkbox"/> <i>Existing pier and beam</i>				
<b>Septic Tanks</b> <input type="checkbox"/> <i>Septic tanks visually identified</i> <input checked="" type="checkbox"/> <i>No visual evidence of septic tank</i>				
<b>Wells</b> <input type="checkbox"/> <i>Well visually identified</i> <input checked="" type="checkbox"/> <i>No visual evidence of well</i>				
<b>Vegetation, Trash or Debris Removal</b> <input type="checkbox"/> <i>Planting and debris &lt;10 cubic yards</i> <input type="checkbox"/> <i>Planting and debris &gt; 10 cubic yards</i>				
<b>Existing Fences on Site</b> <input checked="" type="checkbox"/> <i>Chain Link Fence</i> <input type="checkbox"/> <i>Wood Fence</i> <input type="checkbox"/> <i>Wrought Iron/Metal Fence</i>				
<b>Power Poles - Front of Lot/Back of Lot</b> <input type="checkbox"/> <i>Power pole located at front of lot</i> <input type="checkbox"/> <i>Power pole located in ROW at back of lot</i> <input checked="" type="checkbox"/> <i>No power pole visible on lot</i>				
<b>Drainage</b> <input type="checkbox"/> <i>Lot visibly slopes from back to front</i> <input type="checkbox"/> <i>Lot visibly slopes from front to back</i> <input checked="" type="checkbox"/> <i>Can't tell/Unable to visually determine slope</i>				

**Land Assemblage Redevelopment Authority RFP**  
**Attachment L**  
**Lot Inspections**

<b>Area</b>	<b>HCAD</b>	<b>COH Tract #:</b>	<b>Survey Date:</b>
Third Ward	0192060000012	2562	May 18, 2006

<b>Address No.</b>	<b>Prefix</b>	<b>Street Name</b>	<b>St. Type</b>	<b>Suffix</b>
3616		ST CHARLES		

<b>Curb Cut</b>	
<b>Lot A (left)</b>	<input checked="" type="checkbox"/> Existing Curb Cut <input type="checkbox"/> No existing curb cut
<b>Lot B (If applicable-right)</b>	<input type="checkbox"/> Existing curb cut <input type="checkbox"/> No existing curb cut <input type="checkbox"/> Parcel is only one lot
<b>Lot C (If applicable-furthest right)</b>	<input type="checkbox"/> Existing curb cut <input type="checkbox"/> No existing curb cut <input type="checkbox"/> Parcel is only one lot
<b>Street Edge (Prevailing on Street)</b> <input type="checkbox"/> Sidewalks <input type="checkbox"/> Ditch and Culverts	
<b>Trees Located in Right-of-Way</b> <input type="checkbox"/> No trees observed in ROW <input type="checkbox"/> Less than 3 trees <input type="checkbox"/> Greater than 3 trees	
<b>Trees (&gt;8" Caliper located on Site)</b> <input checked="" type="checkbox"/> No trees <input type="checkbox"/> Less than 3 trees <input type="checkbox"/> Greater than 3 trees	
<b>Existing Slab or Paving Removal</b> <input checked="" type="checkbox"/> Existing slab/pavement <10'-0" x 10'-0" <input type="checkbox"/> Existing slab/pavement >10'-0" x 10'-0" <input type="checkbox"/> Existing pier and beam	
<b>Existing Building Removal</b> <input type="checkbox"/> Existing structure <10'-0" x 10'-0" <input type="checkbox"/> Existing structure >10'-0" x 10'-0" <input type="checkbox"/> Existing pier and beam	
<b>Septic Tanks</b> <input type="checkbox"/> Septic tanks visually identified <input checked="" type="checkbox"/> No visual evidence of septic tank	
<b>Wells</b> <input type="checkbox"/> Well visually identified <input checked="" type="checkbox"/> No visual evidence of well	
<b>Vegetation, Trash or Debris Removal</b> <input type="checkbox"/> Planting and debris <10 cubic yards <input type="checkbox"/> Planting and debris > 10 cubic yards	
<b>Existing Fences on Site</b> <input type="checkbox"/> Chain Link Fence <input type="checkbox"/> Wood Fence <input type="checkbox"/> Wrought Iron/Metal Fence	
<b>Power Poles - Front of Lot/Back of Lot</b> <input type="checkbox"/> Power pole located at front of lot <input type="checkbox"/> Power pole located in ROW at back of lot <input checked="" type="checkbox"/> No power pole visible on lot	
<b>Drainage</b> <input type="checkbox"/> Lot visibly slopes from back to front <input type="checkbox"/> Lot visibly slopes from front to back <input checked="" type="checkbox"/> Can't tell/Unable to visually determine slope	



**Land Assemblage Redevelopment Authority RFP**  
**Attachment L**  
**Lot Inspections**

<b>Area</b>	<b>HCAD</b>	<b>COH Tract #:</b>	<b>Survey Date:</b>
Third Ward	0101620000007	2561	May 18, 2006

<b>Address No.</b>	<b>Prefix</b>	<b>Street Name</b>	<b>St. Type</b>	<b>Suffix</b>
3127		TRULLEY		

<b>Curb Cut</b> <b>Lot A (left)</b> <input checked="" type="checkbox"/> <i>Existing Curb Cut</i> <input type="checkbox"/> <i>No existing curb cut</i> <b>Lot B (If applicable-right)</b> <input type="checkbox"/> <i>Existing curb cut</i> <input type="checkbox"/> <i>No existing curb cut</i> <input type="checkbox"/> <i>Parcel is only one lot</i> <b>Lot C (If applicable-furthest right)</b> <input type="checkbox"/> <i>Existing curb cut</i> <input type="checkbox"/> <i>No existing curb cut</i> <input type="checkbox"/> <i>Parcel is only one lot</i>	
<b>Street Edge (Prevailing on Street)</b> <input type="checkbox"/> <i>Sidewalks</i> <input type="checkbox"/> <i>Ditch and Culverts</i>	
<b>Trees Located in Right-of-Way</b> <input type="checkbox"/> <i>No trees observed in ROW</i> <input type="checkbox"/> <i>Less than 3 trees</i> <input type="checkbox"/> <i>Greater than 3 trees</i>	
<b>Trees (&gt;8" Caliper located on Site)</b> <input type="checkbox"/> <i>No trees</i> <input type="checkbox"/> <i>Less than 3 trees</i> <input checked="" type="checkbox"/> <i>Greater than 3 trees</i>	
<b>Existing Slab or Paving Removal</b> <input type="checkbox"/> <i>Existing slab/pavement &lt;10'-0" x 10'-0"</i> <input checked="" type="checkbox"/> <i>Existing slab/pavement &gt;10'-0" x 10'-0"</i> <input type="checkbox"/> <i>Existing pier and beam</i>	
<b>Existing Building Removal</b> <input type="checkbox"/> <i>Existing structure &lt;10'-0" x 10'-0"</i> <input type="checkbox"/> <i>Existing structure &gt;10'-0" x 10'-0"</i> <input type="checkbox"/> <i>Existing pier and beam</i>	
<b>Septic Tanks</b> <input type="checkbox"/> <i>Septic tanks visually identified</i> <input checked="" type="checkbox"/> <i>No visual evidence of septic tank</i>	
<b>Wells</b> <input type="checkbox"/> <i>Well visually identified</i> <input checked="" type="checkbox"/> <i>No visual evidence of well</i>	
<b>Vegetation, Trash or Debris Removal</b> <input type="checkbox"/> <i>Planting and debris &lt;10 cubic yards</i> <input type="checkbox"/> <i>Planting and debris &gt; 10 cubic yards</i>	
<b>Existing Fences on Site</b> <input type="checkbox"/> <i>Chain Link Fence</i> <input type="checkbox"/> <i>Wood Fence</i> <input type="checkbox"/> <i>Wrought Iron/Metal Fence</i>	
<b>Power Poles - Front of Lot/Back of Lot</b> <input checked="" type="checkbox"/> <i>Power pole located at front of lot</i> <input type="checkbox"/> <i>Power pole located in ROW at back of lot</i> <input type="checkbox"/> <i>No power pole visible on lot</i>	
<b>Drainage</b> <input type="checkbox"/> <i>Lot visibly slopes from back to front</i> <input type="checkbox"/> <i>Lot visibly slopes from front to back</i> <input checked="" type="checkbox"/> <i>Can't tell/Unable to visually determine slope</i>	

**Land Assemblage Redevelopment Authority RFP**  
**Attachment L**  
**Lot Inspections**

<b>Area</b>	<b>HCAD</b>	<b>COH Tract #:</b>	<b>Survey Date:</b>
Third Ward	0572130000002	2560	May 18, 2006

<b>Address No.</b>	<b>Prefix</b>	<b>Street Name</b>	<b>St. Type</b>	<b>Suffix</b>
3004		WEBSTER	CT	

<b>Curb Cut</b> <b>Lot A (left)</b> <input type="checkbox"/> <i>Existing Curb Cut</i> <input checked="" type="checkbox"/> <i>No existing curb cut</i> <b>Lot B (If applicable-right)</b> <input type="checkbox"/> <i>Existing curb cut</i> <input type="checkbox"/> <i>No existing curb cut</i> <input type="checkbox"/> <i>Parcel is only one lot</i> <b>Lot C (If applicable-furthest right)</b> <input type="checkbox"/> <i>Existing curb cut</i> <input type="checkbox"/> <i>No existing curb cut</i> <input type="checkbox"/> <i>Parcel is only one lot</i>	
<b>Street Edge (Prevailing on Street)</b> <input checked="" type="checkbox"/> <i>Sidewalks</i> <input type="checkbox"/> <i>Ditch and Culverts</i>	
<b>Trees Located in Right-of-Way</b> <input type="checkbox"/> <i>No trees observed in ROW</i> <input type="checkbox"/> <i>Less than 3 trees</i> <input type="checkbox"/> <i>Greater than 3 trees</i>	
<b>Trees (&gt;8" Caliper located on Site)</b> <input checked="" type="checkbox"/> <i>No trees</i> <input type="checkbox"/> <i>Less than 3 trees</i> <input type="checkbox"/> <i>Greater than 3 trees</i>	
<b>Existing Slab or Paving Removal</b> <input type="checkbox"/> <i>Existing slab/pavement &lt;10'-0" x 10'-0"</i> <input type="checkbox"/> <i>Existing slab/pavement &gt;10'-0" x 10'-0"</i> <input type="checkbox"/> <i>Existing pier and beam</i>	
<b>Existing Building Removal</b> <input type="checkbox"/> <i>Existing structure &lt;10'-0" x 10'-0"</i> <input type="checkbox"/> <i>Existing structure &gt;10'-0" x 10'-0"</i> <input type="checkbox"/> <i>Existing pier and beam</i>	
<b>Septic Tanks</b> <input type="checkbox"/> <i>Septic tanks visually identified</i> <input checked="" type="checkbox"/> <i>No visual evidence of septic tank</i>	
<b>Wells</b> <input type="checkbox"/> <i>Well visually identified</i> <input checked="" type="checkbox"/> <i>No visual evidence of well</i>	
<b>Vegetation, Trash or Debris Removal</b> <input type="checkbox"/> <i>Planting and debris &lt;10 cubic yards</i> <input type="checkbox"/> <i>Planting and debris &gt; 10 cubic yards</i>	
<b>Existing Fences on Site</b> <input type="checkbox"/> <i>Chain Link Fence</i> <input type="checkbox"/> <i>Wood Fence</i> <input type="checkbox"/> <i>Wrought Iron/Metal Fence</i>	
<b>Power Poles - Front of Lot/Back of Lot</b> <input type="checkbox"/> <i>Power pole located at front of lot</i> <input type="checkbox"/> <i>Power pole located in ROW at back of lot</i> <input checked="" type="checkbox"/> <i>No power pole visible on lot</i>	
<b>Drainage</b> <input type="checkbox"/> <i>Lot visibly slopes from back to front</i> <input type="checkbox"/> <i>Lot visibly slopes from front to back</i> <input checked="" type="checkbox"/> <i>Can't tell/Unable to visually determine slope</i>	